

Roof Condition Report

Inspection Date: 7/20/1969

Inspection Type: Thermal Image Report



PREPARED BY:

Gross Roofing & Sheet Metal LLC 101 N. Barron St., Ste 203 Eaton, OH 45250 937-456-3024

FACILITY:

Sample Address City, State

Building Type: Building Type Neighborhood: Neighborhood

PREPARED FOR:

Contact Title Company Name Email@email.com 111-111-1111



Sections Overview

Sections Overview
Section

Section Outcome

Section

Moderate

Section Outcome

Gross Roofing & Sheet Metal LLC

LC Page 2 of 8


Section

Section Outcome Severity Recommendation

Section Outcome


Moderate

The areas that are bright red are active units. The areas with lighter red are where moisture is present under the membrane.




Section Issue #1 Deficiency #1


Deficiency	Description	Deficiency Effect	Severity	Action
Insulation saturation	Saturation of insulation products can be caused when water infiltrates the system at splits or holes in the roof surface.	Saturation of the insulation products is an indication of a deficiency in the roof membrane that has permitted leakage. R-value and insulation integrity are degraded by the exposure and saturation of the product with moisture.	Moderate	Monitor



Section Issue #2 Deficiency #1


Deficiency	Description	Deficiency Effect	Severity	Action
Insulation saturation	Saturation of insulation products can be caused when water infiltrates the system at splits or holes in the roof surface.	Saturation of the insulation products is an indication of a deficiency in the roof membrane that has permitted leakage. R-value and insulation integrity are degraded by the exposure and saturation of the product with moisture.	Moderate	Monitor







Section Issue #3 Deficiency #1

Deficiency	Description	Deficiency Effect	Severity	Action
Uninsulated Wall	The wall isn't insulated from the interior or exterior.	This will cause you to lose a significant amount of heat/air.	Moderate	Monitor








Section Issue #4 Deficiency #1

Deficiency	Description	Deficiency Effect	Severity	Action
Insulation saturation	Saturation of insulation products can be caused when water infiltrates the system at splits or holes in the roof surface.	Saturation of the insulation products is an indication of a deficiency in the roof membrane that has permitted leakage. R-value and insulation integrity are degraded by the exposure and saturation of the product with moisture.	Moderate	Monitor



Section Issue #5 Deficiency #1

Deficiency	Description	Deficiency Effect	Severity	Action
Insulation saturation	Saturation of insulation products can be caused when water infiltrates the system at splits or holes in the roof surface.	Saturation of the insulation products is an indication of a deficiency in the roof membrane that has permitted leakage. R-value and insulation integrity are degraded by the exposure and saturation of the product with moisture.	Moderate	Monitor

